



Rail

Production facility inspection on  
the basis of the agreement in the testing and  
certification rules performed on **2024-04-25**

**Licence holder:**

**Pilz GmbH & Co. KG**  
Felix-Wankel-Str. 2  
73760 Ostfildern  
GERMANY

**Production facility:**

**Kunbus GmbH**  
Heerweg 15 c  
73700 Denkendorf  
GERMANY

This facility manufactures products certified by  
TÜV SÜD PRODUCT SERVICE for the following  
Product Category/ies:

**PxHZ (2Hand), PNOZclassic, PNOZ X,  
PNOZcompact, PNOZelog, PNOZpower,  
PNOZsigma, PZE, SMR (Safety Monitoring  
Relay), PNOZmulti, PNOZmulti 2**

The production facility inspection was conducted  
according to the instructions of TÜV SÜD  
PRODUCT SERVICE. The requirements to a  
faultless and homogeneous fabrication as stated  
in the test and certification rules are met.  
The applied and documented quality assurance  
procedures were found suitable.

The next inspection will be conducted latest in  
**12 months** starting with the date of inspection.

Munich, 2024-10-17

Wolfgang Mayer – TR-RA-MUC